


Gauge Head Linear Sensor

Travel	
mm of stroke	Value

Electrical Interface	
Input	Output
+ 5 V dc	See below
	A

Adjusts not available

Connector / Cable	
Axial M12 Connector	J
Connector - Radial	K
Axial Cable	Lxx
	Please specify cable length in cm.



Please Note: This sensor *must* be used with a Galvanic Isolation Amplifier - See X005 sheet for Output options.